

F-105 Aircrew Names On the Vietnam Wall

	Panel	Line	Loss Date	Name/ Description/ Crash Coordinates	Unit/ Base/ Acft
1	Adams	06E 122	19-Apr-66	1Lt Lee Aaron "Larry" Adams 333 TFS pilot was KIA in the crash. Hit by gunfire while strafing two trucks. Crashed near Dong Hoi in RP-1, North Vietnam. 17-36-00-N 106-21-57E	333 TFS Takhli F-105D 624330
2	Allee	36W 55	21-Dec-68	Capt Richard Kenneth Allee 354 TFS pilot was MIA after crash. Awarded AF Cross. Hit by AAA while attacking a troop position in Laos. Crashed in Laos. 17-30-40N 105-39-50E	354 TFS Takhli F-105D 610089
3	Allinson	09E 129	12-Aug-66	Capt David Jay Allinson 354 TFS pilot ejected. KIA. Hit by 37/57-mm AAA while attacking a road near Yen Bai. Crashed in RP-6A, North Vietnam. 21-49N 104-42E	354 TFS Takhli F-105D 610156
4	Ammon	10E 126	21-Sep-66	Capt Glendon Lee Ammon 357 TFS pilot ejected on his 60th mission. MIA. Hit by 85-mm AAA while attacking the Dap Cau RR and highway bridge (JCS 16). Crashed in RP-6A, North Vietnam. 21-15N 106-10E	357 TFS Takhli F-105D 624371
5	Asire	13E 20	08-Dec-66	Lt Col Donald Henry Asire The 354 TFS Commander was KIA. Hit by 37-mm (possibly MiG-21) before reaching their target, JCS-19, the Yen Vien RR Classification Yard. Crashed in RP-6A, North Vietnam. 21-40N 105-37E	354 TFS Takhli F-105D 591725
6	Austin	16E 109	19-Mar-67	Lt Col Joseph Clair Austin 34 TFS Commander was MIA. Hit by unknown gunfire while attacking a roadway in the Mu Gia Pass. Crashed in RP-1, North Vietnam. 17-47N 105-45E	34 TFS Korat F-105D 610123
7	Bailey	07E 44	10-May-66	Capt John Edward "Jack" Bailey 469 TFS pilot was KIA in the crash. Hit by unknown gunfire while diving to a target. Crashed in RP-1, North Vietnam. 17-25N 106-42E	469 TFS Korat F-105D 624255
8	Balcom	07E 61	15-May-66	Capt Ralph Carol Balcom 421 TFS pilot was MIA after rescue forces conducted extensive search. Lost due to unknown causes (combat associated) after attacking a bridge, 17 mi south of Dong Hoi, NVN. Initially reported as crashed in RP-1, NVN. Location later changed to Laos. 17-22N 106-30E	421 TFS Korat F-105D 610174
9	Barthelmas, Jr.	02E 44	27-Jul-65	Capt William Jennings "Bart" Barthelmas, Jr. 357 TFS pilot was killed in the crash. Hit by heavy gunfire near SAM Site 6 in RP-6A, NVN. Crashed south of Udom RTAFB, Thailand, after a mid-air collision with his flight lead in F-105D 62-4298. 17-00N 102-40E	357 TFS Korat F-105D 610177
10	Bass	60E 8	14-May-68	Maj Seymour R. Bass 34 TFS pilot died in mid-air crash with his flight lead. Operational loss. Mid-air collision with his flight lead in F-105D 60-0428. Crashed 93 NM NE of Korat RTAFB, Thailand. 15-35N 103-35E	34 TFS Korat F-105D 610132
11	Begley	13E 13	05-Dec-66	Maj Burriss Nelson Begley 421 TFS pilot was MIA then KIA. As part of an Iron Hand flight hunting for SAM sites, he was hit by MiG-17 gunfire while en route to the target. Crashed in RP-5, North Vietnam, approximately 15 miles SE of Yen Bay. 21-35N 105-08E	421 TFS Korat F-105D 624331
12	Bennett	25E 81	02-Sep-67	Maj William George Bennett 333 TFS pilot was MIA then KIA. Rescue attempt was suspended. Hit by unknown gunfire near Route 137 in NVN. Crashed approximately 20 nautical miles west of Dong Hoi in RP-1, North Vietnam. 17-30-20N 106-15-30E	333 TFS Takhli F-105D 624338
13	Bennett	01E 100	04-Apr-65	Maj Frank Everett Bennett 354 TFS pilot ejected but drowned. Hit by gunfire from a MiG-17 while attacking the Thanh Hoa (Ham Rong) bridge. Crashed at sea off the coast of North Vietnam. 16-03N 108-12E	354 TFS Korat F-105D 591754
14	Beresik	62E 5	31-May-68	Maj Eugene Paul Beresik 34 TFS pilot ejected but rescue failed and was declared KIA. Hit by gunfire while strafing a Tiger Island gun site in RP-1, North Vietnam. Crashed at sea off the coast of North Vietnam. 17-10N 107-20E	34 TFS Korat F-105D 600409

F-105 Aircrew Names On the Vietnam Wall

	Panel	Line	Loss Date	Name/ Description/ Crash Coordinates	Unit/ Base/ Acft
15	Biediger	14E 94	29-Jan-67	Maj Larry William Biediger 354 TFS pilot ejected. KIA. One of the plane's 450-gal tanks took off its stab over the Thai Nguyen RR yard. Crashed in RP-6A 45 nautical miles north of Hanoi, North Vietnam. 21-58N 105-25E	354 TFS Takhli F-105F 624420
16	Bischoff	24E 71	03-Aug-67	Capt John William Bischoff 357 TFS pilot ejected. A rescue helicopter picked him up but he died later. Operational loss. Mid-air collision with F-105D 61-0139 during refueling. Crashed in Laos.	357 TFS Takhli F-105D 624240
17	Blackwood	20E 128	27-May-67	Capt Gordon Byron "Buzz" Blackwood 333 TFS pilot ejected but was MIA. Hit by a SAM while en route to the Bac Giang RR bridge (JCS 18.23). Crashed in RP-6A, North Vietnam. 21-24N 106-15E	333 TFS Takhli F-105D 591723
18	Bogiages, Jr.	30W 10	02-Mar-69	Maj Cristos Constantine Bogiages, Jr. 357 TFS pilot was MIA then KIA. Hit by AAA while attacking a storage area in Laos. Crashed in Laos. 19-23-15N 103-09-00E	357 TFS Takhli F-105D 610109
19	Bosiljevac	04W 69	29-Sep-72	Capt Michael Joseph Bosiljevac 17 WWS EWO ejected but was MIA then KIA. Hit by a SAM while attacking a Fansong radar. Crashed in RP-6A, North Vietnam. 21-02N 105-22E	17 WWS Korat F-105G 638302
20	Bower	02E 47	03-Aug-65	Maj Joseph Edward Bower 421 TFS pilot ejected. KIA. Hit by heavy automatic guns while attacking barges. Crashed in the water off the coast of Vinh, North Vietnam. 18-25N 105-52E	421 TFS Korat F-105D 610098
21	Bowles	03E 14	03-Nov-65	Capt Dwight Pollard Bowles 562 TFS pilot was KIA. Aircraft rolled when only one 3,000-pound bomb released on a bridge. Crashed on a mountain side in RP-5, North Vietnam. 21-16N 104-06E	562 TFS Takhli F-105D 610163
22	Brand	10E 14	17-Aug-66	Maj Joseph William Brand 354 TFS pilot ejected but was MIA then KIA despite rescue attempts. Hit by AAA on a SAM suppression mission to support an attack on a military storage area. Crashed in RP-5, North Vietnam. 20-54N 104-43E	354 TFS Takhli F-105F 638308
23	Brinckmann	12E 18	04-Nov-66	Maj Robert Edwin Brinckmann 13 TFS pilot was KIA. Hit by 37/57-mm AAA while attacking a SAM site. Crashed in RP-6A, North Vietnam, 22 miles SE of Thai Nguyen. 21-24N 106-11E	13 TFS Korat F-105F 638273
24	Britt	28E 64	25-Oct-67	Maj Aquilla Friend Britt 469 TFS pilot was killed in the ground collision with a C-123. Landing accident. Collided with taxiing C-123K 54-0667. Crashed at Tan Son Nhut AB, South Vietnam. 10-49N 106-39E	469 TFS Korat F-105D 591737
25	Brownlee	36W 71	24-Dec-68	Maj Charles Richard "Dick" Brownlee 357 TFS pilot ejected and rescue attempted but he was MIA then KIA. Hit by AAA while attacking a truck in Laos. Crashed near Tchepone, Laos. 17-06-50N 105-55-15E	357 TFS Takhli F-105D 624234
26	Bruch, Jr.	07E 7	29-Apr-66	1Lt Donald William Bruch, Jr. 333 TFS pilot was killed in the crash. Hit by heavy 85-mm AAA near the Thai Nguyen RR yard (JCS 21.11). Crashed in RP-6A, North Vietnam. 21-48N 105-31E	333 TFS Takhli F-105D 624304
27	Brucher	32W 52	18-Feb-69	Capt John Martin Brucher 44 TFS pilot ejected but was KIA. Rescue was attempted but was not successful Hit by 37/57-mm AAA while attacking trucks in a POL storage area in Laos. Crashed in North Vietnam. 17-17-10N 106-12-00E	44 TFS 3 Korat F-105D 600505
28	Bullock	11E 65	10-Oct-66	1Lt Glen Francis Bullock 34 TFS pilot ejected on takeoff when his engine failed but he was killed. His lap belt was found open. Operational loss. Engine failed on take off. Crashed approximately one mile off the end of runway 06 at Korat RTAFB, Thailand. 14-57N 102-08E	34 TFS Korat F-105D 624300

F-105 Aircrew Names On the Vietnam Wall

	Panel	Line	Loss Date	Name/ Description/ Crash Coordinates	Unit/ Base/ A/cft
29	Burdett	30E 13	18-Nov-67	Col Edward Burke Burdett Pilot flying with the 469 TFS was the 388 TFW CC. He became a POW and died in captivity. Hit by a SAM during a COMMANDO CLUB mission against Phuc Yen Airfield (JCS 6). Crashed near Dai Dong in RP-6A, North Vietnam. 21-05N 105-34E	469 TFS Korat F-105D 624221
30	Bush	06E 43	24-Mar-66	Capt Robert Edward "Bob" Bush 421 TFS pilot was KIA. Hit by gunfire or possibly a SAM over North Vietnam. Crashed in a river in RP-1, North Vietnam. 17-42-10N 106-29E	421 TFS Korat F-105D 610095
31	Capling	43W 33	19-Sep-68	Maj Elwyn Rex Capling 469 TFS pilot ejected on his 73rd mission and, despite rescue attempt, he was KIA. Hit in the fuselage by 37-mm AAA while attacking a storage area. Crashed in RP-1, North Vietnam. 17-03N 107-03E	469 TFS Korat F-105D 600428
32	Cappelli	30E 6	17-Nov-67	Maj Charles Edward Cappelli 354 TFS pilot ejected but rescue attempt was unsuccessful and he was KIA. Hit by a SAM while attacking Hanoi's Bac Mai Airfield (JCS 7). Crashed in RP-6A, 40 miles SW of Hanoi, 10 NM SW of Hoa Binh, North Vietnam. 20-44N 105-13E	354 TFS Takhli F-105D 624258
33	Caras	18E 105	28-Apr-67	Capt Franklin Angel Caras 44 TFS pilot ejected. MIA. Hit by MiG-21 gunfire while returning from the Hanoi railroad shops (JCS 20). Crashed in RP-5, North Vietnam. 21-13N 104-18E	44 TFS Korat F-105D 581151
34	Carlock	16E 16	04-Mar-67	Maj Ralph Laurence Carlock 357 TFS pilot was MIA then KIA. Hit by 37-mm AAA while attacking a truck in Laos. Crashed in Laos. 19-29N 104-00E	357 TFS Takhli F-105D 624274
35	Christianson	27W 4	03-Apr-69	Maj Peter Bugbee Christianson 34 TFS pilot ejected but was KIA. A rescue helicopter crew recovered his body. Hit by AAA while attacking a storage area in Laos. Crashed in Laos. 19-34N 103-21E	34 TFS Korat F-105D 624269
36	Cobeil	29E 23	05-Nov-67	Capt Earl Glenn Cobeil 333 TFS EWO ejected and became a POW but died in captivity. Hit by 37-mm AAA while supporting the third attack on Phuc Yen Airfield (JCS 6). Crashed in RP-6A, North Vietnam. 21-22N 105-14E	333 TFS Takhli F-105F 624430
37	Colasuonno	32W 19	12-Feb-69	Maj Vincent Colasuonno 333 TFS pilot ejected at high speed. He was rescued but died from his injuries. Aircraft had flight control problems after attacking a storage area in Laos. Crashed in Thailand. 15-53N 104-24E	333 TFS Takhli F-105D 600417
38	Conley	14E 60	21-Jan-67	Lt Col Eugene Ogden Conley 354 TFS commander was KIA in crash. Awarded AFC. Hit by a SAM while attacking the Thai Nguyen RR yard (JCS 21.11). Crashed in RP-6A, North Vietnam. 21-32N 105-46E	354 TFS Takhli F-105D 624239
39	Cooper	06E 131	24-Apr-66	Lt Col William Earl Cooper 469 TFS commander was MIA. Awarded Air Force Cross. Hit by a SAM en route to the Phu Lang Thuong (Bac Giang) Bridge (JCS 18.23). Crashed in RP-6A, North Vietnam. 21-30N 106-04E	469 TFS Korat F-105D 610051
40	Cushman	11E 13	25-Sep-66	Capt Clifton Emmet Cushman 469 TFS pilot ejected. KIA. Hit by 57-mm AAA while attacking AAA gun positions. Crashed in RP-6A, North Vietnam, 26 miles NE of Bac Giang. 21-38N 106-27E	469 TFS Korat F-105D 624341
41	Dardeau, Jr.	30E 14	18-Nov-67	Maj Oscar Moise Dardeau, Jr. 44 TFS pilot was KIA. Lead in WW flight hit by an AAM from a MiG-21 over Phuc Yen Airfield (JCS 6) during a COMMANDO CLUB strike. Crashed in RP-5, North Vietnam. 21-38N 105-12E	44 TFS 3 Korat F-105F 638295
42	Diamond	09E 38	19-Jul-66	1Lt Stephen Whitman Diamond 354 TFS pilot ejected. MIA. Hit by MiG-17 gunfire en route to a POL target. Crashed in RP-6A, North Vietnam. 21-17N 105-42E	354 TFS Takhli F-105D 591755

F-105 Aircrew Names On the Vietnam Wall

	Panel	Line	Loss Date	Name/ Description/ Crash Coordinates	Unit/ Base/ Acft
43	Dice	15W 39	08-Dec-69	Maj Carl Richard Dice 357 TFS pilot died in the crash landing. Hit by 12.7 or 14.5-mm AAA in the left wing while attacking a storage area in Northern Laos. Hit in Laos. Crash landed at Udom RTAFB, Thailand. 17-22N 102-48E	357 TFS Takhli F-105F 638352
44	Diehl, Jr.	29E 40	07-Nov-67	Maj William Calvin Diehl, Jr. 469 TFS pilot ejected but rescue was unsuccessful and he became a POW. He died in captivity. Hit by 37/57-mm AAA while attacking the Lang Giai RR yard. Crashed in RP-6B, North Vietnam. 21-35N 106-45E	469 TFS Korat F-105D 600430
45	Dinan III	29W 62	17-Mar-69	1Lt David Thomas Dinan III 34 TFS pilot ejected but was KIA. A rescue attempt confirmed his death but did not retrieve his body. Hit by AAA while strafing a target in Laos. Crashed in Laos. 19-23N 103-37E	34 TFS 3 Korat F-105D 610104
46	Dodge	23E 13	05-Jul-67	Maj Ward Kent Dodge 357 TFS pilot became a POW and died in captivity. Hit by 85-mm AAA while attacking the Vu Chua RR yard south. Crashed in RP-6A, North Vietnam. 21-33N 106-22E	357 TFS Takhli F-105D 610042
47	Dudash	18E 92	26-Apr-67	Maj John Francis Dudash 333 TFS pilot was KIA in the crash. Hit by a SAM on an Iron Hand mission against the Hanoi transformer station (JCS 82.24). Crashed in RP-6A, North Vietnam. 21-30N 105-26E	333 TFS Takhli F-105F 638277
48	Dyczkowski	08E 129	23-Apr-66	Capt Robert Raymond "Dizzy" Dyczkowski 421 TFS pilot was MIA on his 99th mission. Hit by gunfire near the Phu Lang Thuong (Bac Giang) Bridge (JCS 18.23). Crashed in RP-6A, North Vietnam. 21-28N 106-05E	421 TFS Korat F-105D 610157
49	Earll	11E 95	21-Oct-66	Capt David John Earll 469 TFS pilot was KIA on his 76th mission. Hit by unknown gunfire while attacking storage buildings in North Vietnam. Crashed in RP-1, North Vietnam, one mile west of Dong Ban. 17-40N 106-26E	469 TFS Korat F-105D 610057
50	Eaton	10E 4	14-Aug-66	Maj Curtis Abbot Eaton 333 TFS pilot was MIA on his 29th mission. Hit by 37-mm AAA while attacking a POL storage area. Crashed in RP-6A, North Vietnam. 21-55 N 105-55E	333 TFS Takhli F-105D 591763
51	Edmunds, Jr.	40W 43	27-Oct-68	1Lt Robert Clifton Edmunds, Jr. 469 TFS pilot was MIA then KIA. Hit in the fuselage by 37/57-mm AAA while attacking a target at Quang Khe. Crashed in RP-1, North Vietnam. 17-30N 106-12E	469 TFS Korat F-105D 624264
52	Elliot	39E 31	14-Feb-68	Capt Robert Malcolm Elliot 34 TFS pilot ejected and was MIA then KIA. Hit by a SAM while returning from the Hanoi RR and Hwy bridge (JCS 13). Crashed in RP-6B, North Vietnam. 20-45N 105-57E	34 TFS Korat F-105D 600418
53	Evert	29E 49	08-Nov-67	Capt Lawrence Gerald Evert 354 TFS pilot was KIA. Hit by 37-mm AAA while attacking the Dai Loi RR bridge bypass. Crashed in RP-6A, North Vietnam. 21-16N 105-40E	354 TFS Takhli F-105D 610094
54	Fantle III	33E 47	05-Jan-68	Capt Samuel Fantle III 357 TFS EWO ejected and was KIA. Hit by MiG-17 gunfire over the Dong Muc railroad bridge at location 21-27N and 106-14E. Crashed in RP-6A, North Vietnam. 21-33N 106-03-30E	357 TFS Takhli F-105F 638356
55	Farr	02E 44	27-Jul-65	Maj Jack Graham Farr 357 TFS pilot was killed in the crash. Crashed in a mid-air collision with F-105D 61-0177 after bombing SAM Site 6 in North Vietnam. Crashed in Thailand. 15-05N 105-05E	357 TFS Korat F-105D 624298
56	Feneley	07E 48	11-May-66	Capt Francis James "Frank" Feneley 333 TFS pilot KIA in crash. Hit by heavy unknown gunfire while strafing a bridge. Crashed in RP-1, North Vietnam. 17-43N 106-35E	333 TFS Takhli F-105D 624293
57	Fieszal	42W 47	30-Sep-68	Capt Clifford Wayne "Lefty" Fieszal 333 TFS pilot was MIA then KIA. Hit by 37-mm AAA during a roll-in on a SAM site. Crashed in RP-1, North Vietnam. 17-28N 106-32E	333 TFS Takhli F-105F 638317
58	Fitton, Jr.	42E 5	29-Feb-68	Maj Crosley James Fitton, Jr. 44 TFS pilot ejected and was KIA. Hit by a SAM while attacking a Hanoi vehicle facility during an Iron Hand mission. Crashed in RP-6B, North Vietnam. 20-52N 105-46E	44 TFS Korat F-105F 638312

F-105 Aircrew Names On the Vietnam Wall

	Panel	Line	Loss Date	Name/ Description/ Crash Coordinates	Unit/ Base/ A/cft
59	Franklin	10E 4	14-Aug-66	Capt Charles Edward Franklin 421 TFS pilot ejected. MIA. Hit by 37/57mm AAA attacking the La Danh POL storage area. Crashed in RP-6A, North Vietnam. 21-48N 105-50E	421 TFS Korat F-105D 610197
60	Frederick	23E 10	05-Jul-67	Capt William Vandervos Frederick 354 TFS pilot ejected. KIA. Hit by 57-mm AAA while attacking the Cao Nung RR yard. Crashed in RP-6A, North Vietnam. 21-33N 106-54E	354 TFS Takhli F-105D 600454
61	Frederick	16E 84	15-Mar-67	Lt Col Peter Joseph Frederick 357 TFS pilot was MIA. Hit by unknown gunfire over Route 7 in RP-3. Crashed in Laos. (Latitude and Longitude are hit location). 19-27N 104-05E	357 TFS Takhli F-105D 591825
62	Freeman, Jr.	30E 49	23-Oct-67	Maj Earl Marvin Freeman, Jr. 333 TFS pilot was rescued but died of his injuries on 11 Nov 1967. Operational loss. Mid-air collision with F-105D 62-4335 piloted by Capt Rodney W. McLean from the 357 TFS. Crashed southwest of Udorn RTAFB, Thailand. 16-01N 102-11E	333 TFS Takhli F-105D 610181
63	Fullam	27E 64	07-Oct-67	Maj Wayne Eugene Fullam 469 TFS pilot ejected but rescue attempts did not succeed. KIA. Hit in the right wing by 85-mm AAA over Kep RR yard. Crashed in RP-6B, North Vietnam. 21-16N 106-53E	469 TFS Korat F-105D 600444
64	Gauley	14E 5	10-Jan-67	Capt James Paul Gauley 34 TFS pilot ejected but chute failed. KIA. Rescue crew did not recover his body. Hit by unknown gunfire while diving on a supply area in Laos. Crashed in Laos. 19-08N 103-41E	34 TFS Korat F-105D 624265
65	Givens	52E 5	25-Apr-68	Maj Billy R. Givens 34 TFS pilot died in the crash. He was the 388 TFW Chief of Safety. Operational loss due to the pilot's fuel mismanagement. Crashed short of the runway at Korat RTAFB, Thailand. 14-56N 102-05E	34 TFS 3 Korat F-105D 600436
66	Goss	06E 129	23-Apr-66	Maj Bernard Joseph Goss 421 TFS pilot ejected. KIA. Hit by heavy 37/57-mm AAA near the Phu Lang Thuong (Bac Giang) Bridge (JCS 18.23). Crashed in RP-6A, North Vietnam. 21-35N 106-07E	421 TFS Korat F-105D 610048
67	Green	03E 66	16-Nov-65	Capt Donald George Green 469 TFS pilot ejected. KIA. Hit by a SAM over RP-6B, North Vietnam. Crashed at sea near Haiphong Harbor, North Vietnam. 20-42N 107-28E	469 TFS Korat F-105D 624332
68	Grenzebach, Jr.	19E 95	12-May-67	Maj Earl Wilfre Grenzebach, Jr. 357 TFS pilot ejected on his 63rd mission. The attempted rescue was suspended due to weather and no contact. MIA then KIA. Hit by automatic guns while returning from the Nguyen Khe storage complex. Crashed in RP-6A 61 miles NW of Hanoi, North Vietnam. 21-33N 104-52E	357 TFS Takhli F-105D 591728
69	Greskowiak	01E 115	15-May-65	Capt Robert Greskowiak 35 TFS pilot ejected too low and died. Operational loss. Aircraft did not attain sufficient takeoff speed and crashed beyond runway 16 overrun. Crashed in Dong Plub village 6 NM south of Takhli RTAFB, Thailand. 15-13N 100-17W	35 TFS 6 Takhli F-105D 624374
70	Hagerman	29E 30	06-Nov-67	Maj Robert Warren Hagerman 469 TFS pilot was MIA then KIA. Hit by a SAM while attacking Hanoi's Gia Thuong Storage Area. Crashed in RP-6B, North Vietnam. 21-12N 106-14E	469 TFS Korat F-105D 624286
71	Hamilton	04E 123	31-Jan-66	Capt Eugene David Hamilton 469 TFS pilot was declared MIA. Hit by 37-mm AAA (probably) while attacking barges near Vinh. Crashed in RP-2, North Vietnam. 18-31N 105-48E	469 TFS Korat F-105D 610210
72	Hanley	16W 29	04-Nov-69	Capt Larry James Hanley 357 TFS pilot was MIA then KIA. Hit by gunfire while attacking AAA positions in Laos. Crashed in Laos. 17-29N 105-54E	357 TFS Takhli F-105D 591734
73	Harris	42E 6	29-Feb-68	Capt Cleveland Scott Harris 44 TFS EWO ejected and was MIA. Hit by a SAM while attacking a Hanoi vehicle facility during an Iron Hand mission. Crashed in RP-6B, North Vietnam. 20-52N 105-46E	44 TFS Korat F-105F 638312

F-105 Aircrew Names On the Vietnam Wall

	Panel	Line	Loss Date	Name/ Description/ Crash Coordinates	Unit/ Base/ Acft
74	Hartney	33E 48	05-Jan-68	Maj James Cuthbert Hartney 357 TFS pilot ejected on his 104th combat mission and was MIA. Hit by MiG-17 gunfire over the Dong Muc railroad bridge at location 21-27N and 106-14E. Crashed in RP-6A, North Vietnam. 21-33N 106-03-30E	357 TFS Takhli F-105F 638356
75	Hauer	30E 16	18-Nov-67	Maj Leslie John Hauer 469 TFS pilot ejected but was MIA. Hit by a SAM while attacking Phuc Yen Airfield (JCS 6) during a COMMANDO CLUB strike. Crashed in RP-6A, North Vietnam. 21-22N 105-38E	469 TFS Korat F-105D 624283
76	Hawkins	02E 91	20-Sep-65	Capt Edgar Lee Hawkins 67 TFS pilot was KIA in the crash. Hit the top of a mountain while pulling out of rocket pass on a bridge. Crashed in RP-5, North Vietnam. 20-53N 103-37E	67 TFS 1 Korat F-105D 624238
77	Hensley	45E 11	17-Mar-68	Capt Thomas Truett Hensley 469 TFS pilot was KIA. HH-3 helicopter rescue efforts turned up nothing. Hit by a 37-mm AAA barrage while attacking headquarters buildings in Laos. Crashed in Laos. 20-24-40N 104-03-20E	469 TFS Korat F-105D 610162
78	Hestle, Jr.	08E 134	06-Jul-66	Maj Roosevelt L. "Rudy" Hestle, Jr. 13 TFS pilot was MIA. Hit by 57-mm AAA (probably) while attacking a SAM site. Crashed in RP-5, North Vietnam. 21-30N 105-45E	13 TFS Korat F-105F 638286
79	Hornaday, Jr.	46E 47	27-Mar-68	Capt Ralph J. Hornaday, Jr. 469 TFS pilot ejected but died. Operational loss during aborted takeoff. The right main tire failed and the BAK-12 barrier broke. Crashed on the runway at Korat RTAFB, Thailand. 14-56N 102-05E	469 TFS Korat F-105D 600462
80	Horne	34E 49	14-Jan-68	Maj Stanley Henry Horne 469 TFS pilot ejected but rescue efforts were unsuccessful and he was declared MIA. Hit by a MiG-21 AAM over Yen Bai Airfield. Crashed in RP-5, North Vietnam. 21-45N 105-05E	469 TFS Korat F-105D 600489
81	Hrdlicka	01E 121	18-May-65	Capt David Louis Hrdlicka 563 TFS pilot ejected and was captured but died in captivity in Laos. Hit by heavy gunfire over a road in Laos. Crashed near Sam Neua, Laos. 20-23N 104-11E	563 TFS Takhli F-105D 591753
82	Hunter	07E 109	25-May-66	1Lt Robert Gerald "Jerry" Hunter 354 TFS pilot ejected. KIA on his 34th mission. Hit by light automatic weapons fire over Laos. Crashed 25 to 30 miles northeast of Santiau, Laos. 19-35N 103-44E	354 TFS Takhli F-105D 591746
83	Johnson	11E 119	27-Oct-66	Maj Dale Alonzo Johnson 333 TFS pilot KIA in crash. Hit by unknown gunfire while attacking a road bypass. Crashed in RP-1, North Vietnam, 13 NM NW of Dong Hoi. 17-33N 106-27E	333 TFS Takhli F-105D 624396
84	Jones	33E 49	05-Jan-68	Capt William Eugene Jones 469 TFS pilot ejected and was KIA. Hit by 85-mm AAA while attacking Kep Airfield (JCS 9.1). Crashed in RP-6B, North Vietnam. 21-12N 106-28E	469 TFS Korat F-105D 610068
85	Jones, Jr.	01W 1	16-Apr-72	Capt Orvin Clarence Jones, Jr. 17 WWS EWO was MIA. Hit by a SAM while attacking a SAM support site. Crashed in RP-6B, North Vietnam. 20-55N 106-47E	17 WWS Korat F-105G 638342
86	Kahler	22W 47	14-Jun-69	Maj Harold Kahler 354 TFS pilot was MIA then KIA. Hit by 37-mm AAA while attacking a river ford in Laos. Crashed in Laos. 20-10N 103-54E	354 TFS Takhli F-105D 605381
87	Karins, Jr.	16E 60	11-Mar-67	Capt Joseph John Karins, Jr. 357 TFS pilot ejected. KIA. Hit by a SAM while attacking the Thai Nguyen Iron Works (JCS 76.00). Crashed in RP-6A 30 miles north of Hanoi, North Vietnam. 21-34N 105-50E	357 TFS Takhli F-105D 624261
88	Killian, Jr.	02E 99	30-Sep-65	Lt Col Melvin Joseph Killian, Jr. 334 TFS commander KIA. Awarded AFC. Hit by a SAM near the Ninh Binh RR and highway bridge (JCS 10). Crashed in RP-4, North Vietnam. 22-11N 106-02E	334 TFS Takhli F-105D 610117

F-105 Aircrew Names On the Vietnam Wall

	Panel	Line	Loss Date	Name/ Description/ Crash Coordinates	Unit/ Base/ Acft
89	King	27E 44	03-Oct-67	Maj Ronald Runyan King 333 TFS pilot was killed after ejecting when he became entangled in his chute. Rescue attempts failed to recover his body. Operational loss. Aircraft caught fire after attempting to refuel. Crashed in the Tonkin Gulf 52 NM east of Dong Hoi, North Vietnam. 17-32N 107-30E	333 TFS Takhli F-105D 591824
90	Klenda	02E 85	17-Sep-65	1Lt Dean Albert Klenda 67 TFS pilot ejected but was KIA. Rescue efforts were suspended at 2400L. Hit by moderate 37-mm AAA while attacking a barracks building. Crashed near Son La in RP-5, North Vietnam. 21-08N 104-14E	67 TFS 1 Korat F-105D 624247
91	Klinck	30E 28	19-Nov-67	Capt Harrison Hoyt Klinck 469 TFS pilot was MIA. Hit by a SAM while attacking the Thuy Phoung Barge Yard. Crashed in RP-6A, North Vietnam. 21-05N 105-30E	469 TFS Korat F-105D 610208
92	Kline	12E 10	02-Nov-66	Maj Robert Earl Kline 421 TFS pilot was MIA. Hit by unknown gunfire while strafing a train. Crashed in RP-5, North Vietnam. 22-04N 104-28E	421 TFS Korat F-105D 600469
93	Koontz, Jr.	48W 33	17-Aug-68	Capt Nobe Ray Koontz, Jr. 469 TFS pilot drowned when aircraft flipped over into puddle. Local Base Rescue HH-43B helicopter responded but could not extract pilot from wreckage. Operational loss. Drag chute failed to release and the aircraft was damaged by the mid-field M-21 barrier. Crashed 100 feet from the south end of the overrun to runway 17R at Da Nang AB, South Vietnam. 16-03N 108-12E	469 TFS Korat F-105D 610219
94	Kosko	02E 44	27-Jul-65	Capt Walter B. Kosko 563 TFS pilot ejected. Initially declared MIA then KIA. Hit by heavy 37-mm AAA while attacking SAM site No 7 in RP-6A, NVN. Crashed in RP-5, North Vietnam. 21-04N 105-18E	563 TFS Takhli F-105D 624257
95	Leetun	10E 107	17-Sep-66	Capt Darel Dean Leetun 13 TFS pilot was KIA in the crash. Awarded the AFC. Hit by 37/57-mm AAA while attacking the Cao Nung highway bridge (JCS 18.24). Crashed in RP-6A, North Vietnam. 21-33N 106-30E	13 TFS Korat F-105D 624280
96	Lehnhoff, Jr.	30E 16	18-Nov-67	Capt Edward William "Tiny" Lehnhoff, Jr. 44 TFS EWO was MIA. Lead in WW flight hit by an AAM from a MiG-21 over Phuc Yen Airfield (JCS 6) during a COMMANDO CLUB strike. Crashed in RP-5, North Vietnam. 21-38N 105-12E	44 TFS 3 Korat F-105F 638295
97	Lewis, Jr.	09E 48	20-Jul-66	Capt Merrill Raymond Lewis, Jr. 34 TFS pilot ejected. MIA. ("Rosco's" master) Hit by 85-mm AAA near the Vu Chua RR bridge (JCS 18.74). Crashed in RP-6A, North Vietnam. 21-34N 106-40E	34 TFS Korat F-105D 624308
98	Lillund	27E 49	05-Oct-67	Capt William Allan Lillund 13 TFS Ryan's Raider EWO KIA. Hit by unknown gunfire near the Lang Con RR bridge (JCS 18.26) during a Ryan's Raider mission. Crashed in RP-5, North Vietnam. N/L N/L	13 TFS 3 Korat F-105F 638346
99	Magnusson, Jr.	01E 100	04-Apr-65	Capt James A. Magnusson, Jr. 354 TFS pilot was KIA. Hit by MiG-17 gunfire near the Thanh Hoa (Ham Rong) Bridge (JCS 14). Crashed in RP-4, North Vietnam. 19-28N 105-57E	354 TFS Korat F-105D 591764
100	Mahan	11W 28	20-Apr-70	Capt Douglas Frank Mahan 333 TFS pilot was MIA. Hit by small arms fire while attacking two howitzers in Laos. Crashed in Laos. 19-45N 103-16E	333 TFS Takhli F-105D 600451
101	Mallon	14W 76	28-Jan-70	Capt Richard Joseph Mallon 354 TFS pilot ejected but was KIA. Hit by AAA while pulling up from attacking a SAM site. Crashed in RP-1, North Vietnam. 17-53N 105-51E	354 TFS Takhli F-105G 638329
102	Martin	52E 36	15-Jul-68	Capt Larry Eugene Martin 44 TFS EWO ejected and was KIA. Hit by 37-mm AAA while attacking a suspected SAM site. Crashed in RP-1, North Vietnam. 17-29N 106-38E	44 TFS 3 Korat F-105F 638353

F-105 Aircrew Names On the Vietnam Wall

	Panel	Line	Loss Date	Name/ Description/ Crash Coordinates	Unit/ Base/ Acft
103	Mateja	01W 1	16-Apr-72	Capt Allen Paul Mateja 17 WWS pilot was MIA. Hit by a SAM while attacking a SAM support site. Crashed in RP-6B, North Vietnam. 20-55N 106-47E	17 WWS Korat F-105G 638342
104	Maxwell	44W 38	12-Sep-68	Maj Samuel Chapman "Max" Maxwell 357 TFS pilot was MIA. Hit by AAA while strafing a boat on the Ron River. Crashed in RP-1, North Vietnam. 17-52-45N 106-23-52E	357 TFS Takhli F-105D 591762
105	McCleary	03E 22	05-Nov-65	Lt Col George Carlton McCleary 357 TFS Commander was KIA. Hit by a SAM during a SAM suppression mission. Crashed in RP-4, North Vietnam. 20-13N 105-43E	357 TFS Korat F-105D 624342
106	McCurdy	06E 115	15-Apr-66	Capt John Anthony McCurdy 469 TFS pilot died in heavy-weight crash landing at Korat. Operational loss. Engine problem and overweight high-speed landing. Crashed while attempting to land at Korat RTAFB, Thailand. 14-56N 102-05E	469 TFS Korat F-105D 581158
107	McDaniel, Jr.	27E 49	05-Oct-67	Maj Morris Larosco McDaniel, Jr. 13 TFS Ryan's Raider pilot KIA. Hit by unknown gunfire near the Lang Con RR bridge (JCS 18.26) during a Ryan's Raider mission. Crashed in RP-5, North Vietnam. N/L N/L	13 TFS 3 Korat F-105F 638346
108	McIntire	02W 85	10-Dec-71	Lt Col Scott Winston McIntire 17 WWS EWO ejected but was MIA then KIA. Hit by a SAM near Mu Gia Pass in Laos. Crashed in Laos. 17-42N 105-45E	17 WWS Korat F-105G 638326
109	McLean	28E 56	23-Oct-67	Capt Rodney W. McLean 357 TFS pilot died in the crash on his 6th mission. Operational loss. Mid-air collision with F-105D 61-0181 piloted by Maj Earl W. Freeman, Jr. from the 333 TFS. Crashed southwest of Udorn RTAFB, Thailand. 16-01N 102-11E	357 TFS Takhli F-105D 624335
110	Mearns	12E 55	11-Nov-66	Maj Arthur Stewart Mearns 354 TFS pilot on TDY from 80 TFS was KIA. Hit by gunfire after attacking the Bac Le RR yard. Crashed in RP-6B, North Vietnam, approximately 32 miles NE of Hanoi. 21-14N 107-05E	80 TFS 3 Takhli F-105D 624313
111	Metz	50E 6	15-Apr-68	Maj James Hardin Metz 34 TFS pilot ejected but rescue efforts were unsuccessful. He died as a POW. Hit by 37/57-mm AAA during an armed reconnaissance mission. Crashed 20 miles north of Dong Hoi in RP-1, North Vietnam. 17-40N 106-25E	34 TFS 3 Korat F-105D 610206
112	Meyer	18E 95	26-Apr-67	Capt William Michael Meyer 469 TFS pilot was KIA. Hit by heavy AAA over the Hanoi RR & Highway bridge (JCS 13). Crashed in RP-6A, North Vietnam. 21-04N 105-54E	469 TFS Korat F-105D 581153
113	Miller	03E 45	12-Nov-65	Capt William "Nasty" Ned Miller 562 TFS pilot died. A bomb with a VT fuze exploded under the aircraft while en route to the target. Crashed 55 nautical miles on 272-degree radial from Udorn, Thailand.	562 TFS Takhli F-105D 624218
114	Milliman, Jr.	12E 51	10-Nov-66	Maj Dain W. Milliman, Jr. 469 TFS pilot died. Operational loss. Engine lost power on takeoff. Crashed on takeoff 500 feet off the end of the overrun on runway 06 at Korat RTAFB, Thailand. 14-57N 102-08E	469 TFS Korat F-105D 624288
115	Mongillo	32E 15	17-Dec-67	Capt Paul John Mongillo 44 TFS EWO died of wounds when CBU pellet penetrated rear cockpit canopy and his helmet. 44 TFS EWO struck by a pellet from a CBU jettisoned by a plane that was jumped by MiGs. Pilot Maj Robert S. Beal made emergency landing at Udorn.	44 TFS 3 Korat F-105F 638347
116	Moorberg	13E 5	02-Dec-66	Capt Monte Larue Moorberg 469 TFS pilot was killed in the crash. Awarded the AFC. Hit by 37-mm AAA while attacking the Phuc Yen POL storage area (JCS 51.10). Crashed in RP-6A, North Vietnam. 21-15N 105-32E	469 TFS Korat F-105D 591820

F-105 Aircrew Names On the Vietnam Wall

	Panel	Line	Loss Date	Name/ Description/ Crash Coordinates	Unit/ Base/ Aft
117	Moore, Jr.	25E 93	03-Sep-67	Capt Herbert William Moore, Jr. 469 TFS pilot ejected but despite rescue attempts was MIA. Hit by 37/57-mm AAA while attacking the Xom Cul highway bridge. Crashed in RP-1 55 miles NW of Dong Hoi, North Vietnam. 17-56N 105-48E	469 TFS Korat F-105D 610078
118	Morgan	09E 2	06-Jul-66	Capt Charles Elzy "Chuck" Morgan 13 TFS EWO was KIA. Hit by 57-mm AAA (probably) while attacking a SAM site. Crashed in RP-5, North Vietnam. 21-30N 105-45E	13 TFS Korat F-105F 638286
119	Morrill	25E 24	21-Aug-67	Capt Merwin Lamphrey "Mel" Morrill 354 TFS pilot was MIA then KIA. Hit by 37/57-mm AAA while returning from the Yen Vien RR yard (JCS 19). Crashed in RP-6A, North Vietnam. 20-55N 105-56E	354 TFS Takhli F-105D 591720
120	Nelson	09E 48	20-Jul-66	Col William Humphrey Nelson 355 TFW Vice Commander flying with 354 TFS was KIA. Hit by 85-mm AAA or small arms while strafing a truck. Crashed in RP-5, North Vietnam. 20-46N 105-21E	354 TFS Takhli F-105D 610116
121	Newsom	09E 63	23-Jul-66	Maj Benjamin Byrd Newsom 354 TFS EWO was KIA. Hit by a SAM during a Wild Weasel armed recce. Crashed in RP-6A, North Vietnam. 21-05N 105-30E	354 TFS Takhli F-105F 638338
122	O'Grady	18E 12	10-Apr-67	Maj John Francis O'Grady 357 TFS pilot ejected and was MIA then KIA. Rescue attempt was unsuccessful. Hit by 37/57-mm AAA over Mu Gia Pass. Crashed in RP-1 45 miles south of Vinh, North Vietnam. 17-50-05N 105-46-25E	357 TFS Takhli F-105D 624357
123	Panek, Sr.	14W 76	28-Jan-70	Capt Robert Joseph Panek, Sr. 354 TFS EWO ejected but was KIA. Hit by AAA while pulling up from attacking a SAM site. Crashed in RP-1, North Vietnam. 17-53N 105-51E	354 TFS Takhli F-105G 638329
124	Pemberton	09E 64	23-Jul-66	Maj Gene Thomas Pemberton 354 TFS pilot was KIA. Hit by a SAM during a Wild Weasel armed recce. Crashed in RP-6A, North Vietnam. 21-05N 105-30E	354 TFS Takhli F-105F 638338
125	Pitman	19E 99	12-May-67	Capt Peter Potter Pitman 34 TFS Ryan's Raider pilot was KIA. Lost during a night Ryan's Raider mission from unknown causes near the Ron Ferry complex in RP-1. Fireball seen at possible crash site in RP-1, North Vietnam. 17-46N 106-35E	34 TFS Korat F-105F 638269
126	Pogreba	02E 109	05-Oct-65	Maj Dean Andrew Pogreba 36 TFS pilot was KIA on his 35th mission. Hit by 37/57-mm AAA near the Lang Met Highway Bridge (JCS 18.75). Crashed in RP-6B, North Vietnam. 21-31N 106-21E	36 TFS 6 Takhli F-105D 624295
127	Powell	25E 25	21-Aug-67	1Lt Lynn Kesler Powell 354 TFS pilot KIA in crash. Hit by AAA while attacking the Yen Vien RR yard (JCS 19). Crashed in RP-6A, North Vietnam. 21-01N 105-48E	354 TFS Takhli F-105D 600437
128	Reitmann	03E 119	01-Dec-65	Capt Thomas Edward Reitmann 334 TFS pilot was KIA. Hit by heavy 37-mm AAA near the Cao Nung RR Bridge (JCS 18.24). Crashed in RP-6B, North Vietnam. 21-33N 106-29E	334 TFS Takhli F-105D 610182
129	Rex	37W 68	08-Dec-68	1Lt Robert Alan Rex 357 TFS pilot was KIA. Hit by AAA while attacking a truck storage area in Laos. Crashed in Laos. 20-22N 103-51E	357 TFS Takhli F-105D 610150
130	Richter	24E 13	28-Jul-67	1Lt Karl Wendell Richter 44 TFS pilot ejected. He died in the rescue helicopter. Hit by 57-mm AAA while attacking a dirt bridge in RP-1, North Vietnam. Crashed in Laos. 17-41N 105-33E	44 TFS Korat F-105D 624334
131	Russell	31E 42	05-Dec-67	Maj Donald Myrick Russell 333 TFS pilot was KIA. Hit by 37/57-mm AAA while attacking a storage area in Laos. Crashed approximately 11 NM south of Sam Nuea in Laos. 20-14N 104-02-30E	333 TFS Takhli F-105D 591758

F-105 Aircrew Names On the Vietnam Wall

	Panel	Line	Loss Date	Name/ Description/ Crash Coordinates	Unit/ Base/ Acft
132	Sanders	19W 115	25-Aug-69	Maj Steven Roy Sanders 357 TFS pilot was KIA in the crash. Hit by gunfire while attacking troops in a woods in Laos. Crashed in Laos. 19-20N 103-40E	357 TFS Takhli F-105D 591818
133	Schuler, Jr.	02E 124	15-Oct-65	Capt Robert Harry Schuler, Jr. 36 TFS pilot was KIA. Hit after being diverted to rescap for downed wingman, Capt Thomas W. Sima. Crashed in RP-5, North Vietnam. 21-48N 104-46E	36 TFS Takhli F-105D 624305
134	Scungio	12E 25	04-Nov-66	Capt Vincent Anthony Scungio 13 TFS EWO was KIA. Hit by 37/57-mm AAA while attacking a SAM site. Crashed in RP-6A, North Vietnam, 22 miles SE of Thai Nguyen. 21-24N 106-11E	13 TFS Korat F-105F 638273
135	Shattuck, Jr.	20W 55	17-Jul-69	Maj Fredrick William Shattuck, Jr. 333 TFS pilot picked up by a HH-43B rescue helicopter but died 2 days later from burns. Operational loss. The left tire blew out on takeoff roll. Crashed on the runway at Takhli RTAFB, Thailand.	333 TFS Takhli F-105D 624394
136	Silva	14E 96	29-Jan-67	1Lt Claude Arnold "Honey Bear" Jos Silva 354 TFW EWO ejected. KIA. One of the plane's 450-gal tanks took off its stab over the Thai Nguyen RR yard. Crashed in RP-6A 45 nautical miles north of Hanoi, North Vietnam. 21-58N 105-25E	354 TFS Takhli F-105F 624420
137	Singer	10E 15	17-Aug-66	Maj Donald Maurice Singer 354 TFS EWO ejected but was MIA then KIA despite rescue attempts. Hit by AAA on a SAM suppression mission to support an attack on a military storage area. Crashed in RP-5, North Vietnam. 20-54N 104-43E	354 TFS Takhli F-105F 638308
138	Smith	42W 52	30-Sep-68	Maj Howard Horton Smith 333 TFS EWO was MIA then KIA. Hit by 37-mm AAA during a roll-in on a SAM site. Crashed in RP-1, North Vietnam. 17-28N 106-32E	333 TFS Takhli F-105F 638317
139	Smith	05E 128	07-Mar-66	Capt Harold Victor Smith 469 TFS pilot was MIA. Hit by 57-mm AAA over North Vietnam during a SAM search and destroy mission. Crashed in RP-4 approximately 25 miles west of Thanh Hoa, North Vietnam. 19-50N 105-25E	469 TFS Korat F-105D 624410
140	Steen	07E 129	31-May-66	Capt Martin William Steen 469 TFS pilot was KIA after ejecting. Rescue was attempted but pilot not found. Hit by heavy 57-mm AAA near the Yen Bay complex (JCS 44). Crashed in RP-5, North Vietnam. 21-39N 104-40E	469 TFS Korat F-105D 610120
141	Stewart	19E 101	12-May-67	Capt Robert Allan Stewart 34 TFS rear seat Ryan's Raider pilot was MIA then KIA. Lost during a night Ryan's Raider mission from unknown causes near the Ron Ferry complex in RP-1. Fireball seen at possible crash site in RP-1, North Vietnam. 17-46N 106-35E	34 TFS Korat F-105F 638269
142	Stone	02W 103	02-Feb-72	Maj Charles H. "Chuck" Stone 17 WWS pilot died. Operational loss due to a massive fuel leak and fire. Crashed on take off from Korat RTAFB, Thailand.	17 WWS Korat F-105G 638284
143	Sullivan III	08E 73	21-Jun-66	1Lt John Bernard Sullivan III 36 TFS pilot on TDY with the 34 TFS was MIA. Hit twice by heavy 85-mm AAA while attacking the Dao Quan POL storage area (BE 616-01748). Crashed in RP-6A, North Vietnam. 21-24N 106-14E	36 TFS 3 Korat F-105D 624358
144	Swanson, Jr.	21E 109	15-Jun-67	Capt John Willard Swanson, Jr. 34 TFS pilot ejected. Rescue attempts were unsuccessful. MIA. Hit by 37-mm AAA while attacking the Dong Khe RR siding in RP-3, NVN. Crashed at sea 145 miles north of the DMZ in North Vietnam. 19-04N 105-45E	34 TFS 3 Korat F-105D 610213
145	Thomas, Jr.	07E 31	05-May-66	1Lt Kenneth Deane Thomas, Jr. 469 TFS pilot ejected. KIA. Hit by heavy 37/57-mm AAA near the Cao Nung RR bridge (JCS 18.24). Crashed in RP-6B, North Vietnam. 21-33N 106-50E	469 TFS Korat F-105D 610147

F-105 Aircrew Names On the Vietnam Wall

	Panel	Line	Loss Date	Name/ Description/ Crash Coordinates	Unit/ Base/ Acft
146	Thomas, Jr.	04W 131	21-Apr-72	Capt William A. "Bill" Thomas, Jr. 12 TFS pilot parachuted but died. Operational loss during test flight. Pilot flew into clouds, two booms were heard and debris fell from the plane. Crashed in the Pacific Ocean south of Ie Shima Island, Okinawa. 26-40N 127-46E	12 TFS Kaden F-105D 624244
147	Tiffin	09E 54	21-Jul-66	Capt Rainford "Ray" McMaster Tiffin 34 TFS pilot was MIA then KIA. Hit by 37/57-mm AAA near Yen Bai, North Vietnam. Crashed in RP-5, North Vietnam. 21-59N 104-47E	34 TFS 3 Korat F-105D 624227
148	Turose	01W 74	17-Sep-72	1Lt Michael Stephen Turose 17 WWS EWO ejected but was KIA. Hit by a SAM after attacking a Fansong radar in RP-6B, North Vietnam. Crashed at sea off the coast of North Vietnam. 20-38N 107-06E	17 WWS Korat F-105G 638360
149	Underwood	06E 16	16-Mar-66	Maj Paul Gerard Underwood 333 TFS pilot ejected. MIA. Hit by 37-mm AAA (probably) over North Vietnam. Crashed in RP-5 North Vietnam. 21-28N 102-53E	333 TFS Takhli F-105D 600411
150	Waters, Jr.	13E 42	13-Dec-66	Capt Samuel Edwin Waters, Jr. 421 TFS pilot ejected and was KIA. TDY from 12 TFS. Hit by a SAM while attacking the Yen Vien RR classification yard (JCS 19). Crashed in RP-6A, North Vietnam, 3 miles NNE of Thanh Lang. 20-52N 105-25E	421 TFS Korat F-105D 610187
151	Weskamp	18E 84	25-Apr-67	1Lt Robert Larry Weskamp 354 TFS pilot ejected but didn't survive. Hit by 85-mm en route to the Hanoi Transformer Station (JCS 82.24). Crashed in RP-6A, North Vietnam. 21-09N 105-51E	354 TFS Takhli F-105D 624294
152	White	16W 119	24-Nov-69	Capt James Blair White 357 TFS pilot was MIA then KIA. Hit by gunfire while attacking troops in Laos. Crashed in Laos. 19-35N 103-31E	357 TFS Takhli F-105D 610060
153	Williamson	02E 30	07-Jul-65	Capt Don Ira Williamson 12 TFS pilot ejected but was MIA. Hit by automatic weapons near a bridge east of Ha Tinh near Vinh, NVN. Crashed in RP-2, North Vietnam. 18-26N 105-52E	12 TFS 1 Korat F-105D 624232
154	Wistrand	01E 112	09-May-65	Capt Robert Carl Wistrand 563 TFS pilot was KIA. Hit by heavy unknown gunfire while attacking a Mu Gia Pass AAA site during a Steel Tiger mission. Crashed in Laos. 17-45N 105-43E	563 TFS Takhli F-105D 624408
155	Wood	04E 76	16-Jan-66	Capt Don Charles Wood 354 TFS pilot was MIA then KIA. Hit by 37-mm AAA while overflying a AAA site in Laos. Crashed in Laos north of the Plain des Jarres. 19-31N 103-11E	354 TFS Takhli F-105D 591719
156	Woodworth	01E 103	17-Apr-65	Capt Samuel Alexander Woodworth 563 TFS pilot was killed in the crash. Collided with a hill as he fired rockets at the Mu Gia Pass Army Supply and Staging Point (JCS 39.3). Crashed in RP-1, North Vietnam. 17-40N 105-46E	563 TFS Takhli F-105D 610171
157	Zorn, Jr.	01W 74	17-Sep-72	Capt Thomas O'Neal "Zoomer" Zorn, Jr. 17 WWS pilot was KIA. A Navy rescue attempt was unsuccessful. Hit by a SAM after attacking a Fansong radar in RP-6B, North Vietnam. Crashed at sea off the coast of North Vietnam. 20-38N 107-06E	17 WWS Korat F-105G 638360
158	Zukowski	32W 18	11-Feb-69	1Lt Robert John Zukowski 34 TFS pilot was MIA. Hit by 37-mm AAA while attacking a POL storage area in Laos. Crashed in Laos. 17-07N 106-03E	34 TFS 3 Korat F-105D 624256